



Nebraska Department of Natural Resources Field Office Boundaries Map

Dam Inspection Boundaries

- Ord Field Office
- Bridgeport Field Office
- Norfolk Field Office
- Cambridge Field Office
- Lincoln Field Office
- DNR Field Office Location

Surface Water Administration Boundaries

Bridgeport Field Office 729 Main Street P.O. Box 787 Bridgeport, Nebraska 69336-0787 Phone: 308-262-1930 Fax: 308-262-1939	Norfolk Field Office 601 East Benjamin Ave., Suite 101 Norfolk, Nebraska 68701 Phone: 402-370-3377 Fax: 402-371-0653	Lincoln Field Office 301 Centennial Mall South P.O. Box 94676 Lincoln, Nebraska 68509-4676 Phone: 402-471-2363 Fax: 402-471-2900
Cambridge Field Office 622 Patterson P.O. Box 426 Cambridge, Nebraska 69022 Phone: 308-697-3730 Fax: 308-697-3200	Ord Field Office North Highway 11 P.O. Box 251 Ord, Nebraska 68862 Phone: 308-728-3325 Fax: 308-728-9967	